Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy

Inspection Date: 10/25/2024	or and form and any av	seamentation pr	ovided with the mstrane	policy
Owner Information				
Owner Name: Kentwood Park			Contact Person:	
Address: 2302 Maki Rd. Bldg K			Home Phone:	
City: Plant City, FL	Zip: 33563		Work Phone:	
County: Hillsborough	F- 33303		Cell Phone:	
Insurance Company:			Policy #:	
Year of Home: 1987	# of Stories: Two		Email:	
1007				
NOTE: Any documentation used in a accompany this form. At least one ph though 7. The insurer may ask additional transfer of the second	otograph must accompa	ny this form to val	lidate each attribute marked	in questions 3
1. Building Code: Was the structure by the HVHZ (Miami-Dade or Broward A. Built in compliance with the a date after 3/1/2002: Building B. For the HVHZ Only: Built in provide a permit application with C. Unknown or does not meet the Code Covering: Select all roof covering: OR Year of Original Installation/Re	regular description of the requirements of Answer regular types in use. Provide	Building Code (SFI For homes bui MDD/YYYY)/ C-94: Year Built _ uilding Permit Appl "A" or "B" the permit application	BC-94)? It in 2002/2003 provide a peri For homes built in 19 lication Date (MM/DD/YYYY)/_ tion date OR FBC/MDC Produ	nit application with 94, 1995, and 1996/
covering identified.	Permit Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance
_		rroduct Approval#	•	Соприансе
1. Asphalt/Fiberglass Shingle	08/02/2024		2024	
2. Concrete/Clay Tile				
3. Metal	/			
4. Built Up				
				\vdash
A. All roof coverings listed about installation OR have a roofing proofing permit application after C. One or more roof coverings of D. No roof coverings meet the roof. 3. Roof Deck Attachment: What is the A. Plywood/Oriented strand box by staples or 6d nails spaced at shinglesOR- Any system of some mean uplift less than that requir B. Plywood/OSB roof sheathin 24"inches o.c.) by 8d common other deck fastening system or a maximum of 12 inches in the C. Plywood/OSB roof sheathin 24"inches o.c.) by 8d common decking with a minimum of 2 n	permit application date on a ami-Dade Product Approv 9/1/1994 and before 3/1/2 do not meet the requirement equirements of Answer "A re weakest form of roof deard (OSB) roof sheathing at 6" along the edge and 12 crews, nails, adhesives, othed for Options B or C belong with a minimum thickne nails spaced a maximum of the control of the	or after 3/1/02 OR to ral listing current at 2002 OR the roof is onts of Answer "A" of A" or "B". ck attachment? attached to the roof of	truss/rafter (spaced a maximu-Batten decking supporting vystem or truss/rafter spacing tached to the roof truss/rafter (sfieldOR-Any system of screquivalent or greater resistance to 103 psf. ached to the roof truss/rafter (sfieldOR-Dimensional lumb	2004 or later. ne HVHZ only) a later. m of 24" inches o.c.) wood shakes or wood hat has an equivalent paced a maximum of laws, nails, adhesives, than 8d nails spaced paced a maximum of er/Tongue & Groove
Any system of screws, nails, ad	lhesives, other deck fasten	ing system or truss		
Inspectors Initials Property Ad	Idress_ 2302 Maki Rd. B	iag K		

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure. OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155 Page 1 of 4

			greater res 2 psf.	sistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least
			•	ed Concrete Roof Deck.
			Other:	
		F.	Unknown	n or unidentified.
		G.	No attic a	access.
4.		et c	of the insic	tachment: What is the <u>WEAKEST</u> roof to wall connection? (Do not include attachment of hip/valley jacks within de or outside corner of the roof in determination of WEAKEST type)
		A.	Toe Nail	Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
				Metal connectors that do not meet the minimal conditions or requirements of B, C, or D
	Mir	iim	al conditi	ons to qualify for categories B, C, or D. All visible metal connectors are:
			J	Secured to truss/rafter with a minimum of three (3) nails, and
			\checkmark	Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a ½" gap from the blocking or truss/rafter and blocked no more than 1.5" of the truss/rafter, and free of visible severe corrosion.
	√	В.	Clips	1
			✓	Metal connectors that do not wrap over the top of the truss/rafter, or
ı				Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nail position requirements of C or D, but is secured with a minimum of 3 nails.
		C.	Single W	raps Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a
				minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.
		D.	Double V	
				Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, or
				Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.
	Щ	E.	Structura	Anchor bolts structurally connected or reinforced concrete roof.
		F.	Other: _	
	Щ			n or unidentified
		Н.	No attic a	access
5.				What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall of over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).
		A.	Hip Root	
		В.	Flat Root	•
	√	C.	Other Ro	less than 2:12. Roof area with slope less than 2:12 sq ft; Total roof area sq ft of Any roof that does not qualify as either (A) or (B) above.
5.	Sec	А. В.	SWR (also sheathing dwelling No SWR	er Resistance (SWR): (standard underlayments or hot-mopped felts do not qualify as an SWR) so called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the g or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the from water intrusion in the event of roof covering loss. In or undetermined.
ln	spec	tors	s Initials	Property Address 2302 Maki Rd. Bldg K
	Thia .		fination f	orm is valid for up to five (5) years provided no material changes have been made to the structure or

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

7. Opening Protection: What is the weakest form of wind borne debris protection installed on the structure? First, use the table to determine the weakest form of protection for each category of opening. Second, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings and (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart Place an "X" in each row to identify all forms of protection in use for each		Glazed Openings			Non-Glazed Openings		
openi form o	ng type. Check only one answer below (A thru X), based on the weakest of protection (lowest row) for any of the Glazed openings and indicate eakest form of protection (lowest row) for Non-Glazed openings.	Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure		Х	Х	Х		Х
A	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)						
В	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
С	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
	Opening Protection products that appear to be A or B but are not verified						
N	Other protective coverings that cannot be identified as A, B, or C						
Х	No Windborne Debris Protection	Х				X	
sy	minimum, with impact resistant coverings or products listed as wind be stem of the State of Florida or Miami-Dade County and meet the requal ad Large Missile Impact" (Level A in the table above).						
	Miami-Dade County PA 201, 202, and 203						
	Florida Building Code Testing Application Standard (TAS) 20	01 202 and	203				
	American Society for Testing and Materials (ASTM) E 1886:	· · · · · · · · · · · · · · · · · · ·					
	Southern Standards Technical Document (SSTD) 12	anu Astivi	L 1990				
	• For Skylights Only: ASTM E 1886 and ASTM E 1996						
	• For Garage Doors Only: ANSI/DASMA 115	N1 1 '	٠,				
	A.1 All Non-Glazed openings classified as A in the table above, or no Non-C A.2 One or More Non-Glazed openings classified as Level D in the table above X in the table above	-	-	d openings	classified	l as Leve	l B, C, N,
	A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X i	n the table a	bove				
R	Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb I	arge Miss	sile <i>(</i> 2-4	5 lh for s	kvlight	s only)	All Glaz
op in	penings are protected, at a minimum, with impact resistant coverings the product approval system of the State of Florida or Miami-Dade Cr "Cyclic Pressure and Large Missile Impact" (Level B in the table ab ASTM E 1886 and ASTM E 1996 (Large Missile – 4.5 lb.) SSTD 12 (Large Missile – 4 lb. to 8 lb.)	or products	s listed as	s windborn	ne debris	protect	ion devic
	• For Skylights Only: ASTM E 1886 and ASTM E 1996 (Large	e Missile - 2	to 4.5 lb.)				
	B.1 All Non-Glazed openings classified as A or B in the table above, or no N	on-Glazed o	penings e	xist			
	B.2 One or More Non-Glazed openings classified as Level D in the table abo in the table above	ve, and no N	Ion-Glaze	d openings	classified	l as Leve	1 C, N, or 2
	B.3 One or More Non-Glazed openings is classified as Level C, N, or X in th	e table abov	e				
	Exterior Opening Protection- Wood Structural Panels meeting wood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2					are co	vered wi
	C.1 All Non-Glazed openings classified as A, B, or C in the table above, or n C.2 One or More Non-Glazed openings classified as Level D in the table about the table above				classified	l as Leve	l N or X in

C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

Inspectors Initials Property Address 2302 Maki Rd. Bldg K

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

N. Exterior Opening Protection (unverified shutter		
protective coverings not meeting the requirements of A with no documentation of compliance (Level N in the		stems that appear to meet Answer "A" or "B"
N.1 All Non-Glazed openings classified as Level A, B, C,	· · · · · · · · · · · · · · · · · · ·	on-Glazed openings exist
N.2 One or More Non-Glazed openings classified as Leve		
table above		
N.3 One or More Non-Glazed openings is classified as Le	vel X in the table above	
X. None or Some Glazed Openings One or more Glazed	zed openings classified and L	evel X in the table above.
MITIGATION INSPECTIONS MUST Section 627.711(2), Florida Statutes, pro	~	
Qualified Inspector Name: Richard Murphy	License Type:	License or Certificate #: 60
Inspection Company: Murphy's Law Home Inspections, Inc		Phone: 813-228-6631
Qualified Inspector – I hold an active license as		010 220 0001
Home inspector licensed under Section 468.8314, Florida Statu training approved by the Construction Industry Licensing Board Building code inspector certified under Section 468.607, Florid General, building or residential contractor licensed under Section Professional engineer licensed under Section 471.015, Florida S	tes who has completed the statut d and completion of a proficiency a Statutes. on 489.111, Florida Statutes.	
Professional architect licensed under Section 481.213, Florida S		
Any other individual or entity recognized by the insurer as poss verification form pursuant to Section 627.711(2), Florida Statut	sessing the necessary qualification	ns to properly complete a uniform mitigation
Individuals other than licensed contractors licensed under under Section 471.015, Florida Statues, must inspect the statues under s.471.015 or s.489.111 may authorize a diexperience to conduct a mitigation verification inspection. I, Richard Murphy am a qualified inspector (print name) contractors and professional engineers only) I had my empand I agree to be responsible for his/her work. Qualified Inspector Signature: An individual or entity who knowingly or through gross manual individual or entity wh	and I personally performed loyee (through employees or other persons. s the requisite skill, knowledge, and I the inspection or (licensed) perform the inspection of inspector) 5/2024 r fraudulent mitigation verification form is ct to administrative action by the ida Statutes) The Qualified Inspector who chorized mitigation inspector personally bloyee did perform an inspection of the Authorized Representative.
An individual or entity who knowingly provides or utters obtain or receive a discount on an insurance premium to v		
of the first degree. (Section 627.711(7), Florida Statutes)	which the individual of end	ty 15 not entitled committe a misuemeanor
The definitions on this form are for inspection purposes of as offering protection from hurricanes.	nly and cannot be used to ce	ertify any product or construction feature
Inspectors Initials Property Address 2302 Maki R	d. Bldg K	
*This verification form is valid for up to five (5) years pro inaccuracies found on the form.	vided no material changes h	have been made to the structure or

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Page 4 of 4



City of Plant City 302 West Reynolds Street Plant City, FL 33563

PERMIT NUMBER

0724-04876

Issued Date: 8/2/2024

Permit Type: Roof Comm

Property Number	Street Address		
205010.0340	2302 MAKI RD, 70, Plant City FL 33563-7143		
Floor Elevation: Flood Zone:	Jurisdiction		
Owner Information	Applicant Information		
Name: GINGER KING	Name: Krzysztof Szostek		
Address: 2302 MAKI RD UNIT 70	Phone:		
Contractor Information			
Name: NO 1 Home Roofing Inc	Permit Trades Name:		
Address: 35753 US Hwy 19 N	Permit Tradesman Lic #:		
Phone: 727-781-7663	Permit Tradesman Lic #.		
Building Information			
Proposed Use:	Total Sq. Ft:		
Construction Type:	Living Area Sq. Ft:		
Number of Stories:			
Estimated Cost of Construction: \$15,800.00			

Project Description:

UNITS 70-76 Remove existing and install new OC Shingles FL#10674.R19, Peel and Stick Underlayment FL#46297.R2, 40SQS, 5/12

Fees	
HCRF/DCA SURCHARGE - Roof	\$2.00
DBPR/BCAI - Roof	\$2.25
Building - NOC (Notice of Commencement) fee	\$5.00
Building - Re-roof	\$150.00

^{***}AN ADDITIONAL \$5 NOC FEE MAY APPLY***

The permit holder shall agree to comply with all applicable laws regulating the work. Having received a copy of this document and understanding that it is the permit holder's responsibility to inform this office of any change of contractor by completing and submitting a change of contractor form if necessary. I further understand that all inspection requests are to be made by me or my agent.

Ray Parts

Date: 8/2/2024

Signature of Permit Approver

ANY PERMIT ISSUED EXPIRES SIX (6) MONTHS AFTER ISSUANCE IF NO INSPECTIONS HAVE BEEN MADE

TOTAL FEES: \$159.25









Kentwood Park

2302 Maki Rd. Bldg K

Plant City, FL









Kentwood Park

2302 Maki Rd. Bldg K

Plant City, FL

33563